

A. ALL SYSTEMS OPERATED AS DIRECTED BY REFS, NO MALFUNCTIONS INDICATED.

- B. SYSTEM 12B-1 INDICATOR HAD SOLID HALF INCH STROBE AT 180 DEGREES, FOR WHOLE TIME OF ACTIVITY. STROBES FROM SITE SHOWED ABOUT 5 DEGREES OF FANNING WITH GOOD PATTERN, AND REMAINED ABOUT 5 DEGREES UNTIL ABOUT 200 DEGREES OR 7 O'CLOCK, WHERE FAN SPREAD TO ABOUT 15 TO 20 DEGREES. THEN RETURNED TO THE 5 DEGREE SHAPE.
 - C. FANNING APPARENTLY FROM GROUND ENVIRONMENT.
- D. 180 DEGREE STROBE APPARENTLY FROM LEAKAGE INTO 180 DEGREE RECEIVE ANTENNA.
- E. GROUND TESTS WILL BE PERFORMED TO DETERMINE DEGREE OF SUCCESS OF FLIGHT SOON AS 12B TEST MODULATOR AVAILABLE.
- F. CROSS TALKS ON SOME CHANNELS OF MC RECORDER MOSTLY VOICE, CAUSE UNKNOWN. WILL BE INVESTIGATED.

C D O R D T TOR: 092333Z JUN 67